# Giant Resource Recovery - Sumter, Inc.

755 Industrial Road • PO Box 1755 • Sumter, SC 29151 • Phone: (803) 773-1400 • Fax: (803) 773-7423

Fed Ex Tracking Number: 7949 0744 8486

March 6, 2013

Office of Enforcement and Compliance Assurance
Office of Federal Activities
International Compliance Assurance Division (2254A)
Environmental Protection Agency
1200 Pennsylvania Avenue, NW.
Washington, DC 20460

Re: Giant Resource Recovery

EPA ID No. SCD036275626

Manifests for Imported Hazardous Waste

MTN: 000161409GRR

### Dear Sir/Madam:

As required by 40 CFR 264.71(a)(3), Giant Resource Recovery provides the attached copies of manifests for hazardous waste received from foreign sources at our Sumter, South Carolina facility. The contents of the attachment are based on guidance received from the EPA following the July 7, 2010 effective date of the revised regulation. If you have any questions or require additional information, please contact Sheila Buckman Environmental Compliance Manager, at (803) 773-1400.

Sincerely,

Maria T Pike
Records/Manifest Manager

Giant Resource Recovery - Sumter

o: 803-773-1400 x212 c: 803-720-4641 f: 803-773-7423

501 3/11/2013

## FACSIMILE COVER SHEET

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OFFICE OF FEDERAL ACTIVITIES
INTERNATIONAL COMPLIANCE AND ASSURANCE DIVISION
1200 PENNSYLVANIA AVENUE., N.W., Rm.6144
MAIL CODE 2254A
WASHINGTON, D.C. 20460

PHONE NUMBER: 202-564-7111 FAX NUMBER: 202-564-0025

TO: Cecil Hopper

OFFICE: Giant Resources Recovery-Sumter

Giant Resource Recovery - Attalla

PHONE NUMBER:

FAX NUMBER: 803-775-4145

256-538-1836 843-376-2529

FROM:

Jean Shaw

Import/Export Program

DATHMAY 2 4 2012

# OF PAGES:

(including cover)

COMMENTS:



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY WASHINGTON, D.C. 20460

OFFICE OF ENFORCEMENT AND COMPLIANCE ASSURANCE

May 24, 2012

CECIL HOPPER GIANT RESOURCE RECOVERY-SUMTER, INC. 755 INDUSTRIAL ROAD, P.O. BOX 1755 SUMTER, SC 29151

> Re: Foreign Notice ID: 525984 EPA Notice ID: 004872/5I/12

## Dear CECIL HOPPER:

Under the requirements in 40 CFR §§ 264.71(a)(3) and 265.71(a)(3) owners and operators of hazardous waste treatment, storage, and disposal facilities receiving hazardous waste from a foreign source must submit a copy of documentation confirming EPA's consent to the import of the hazardous waste at the same time they submit a copy of the RCRA hazardous waste manifest within thirty (30) days of each import shipment's delivery.

This letter serves as EPA's import consent documentation for the export of (See Below) from FIELDING CHEMICAL TECHNOLOGIES, INC., 3575 MAVIS ROAD, MISSISSAUGA, ON, CANADA to GIANT RESOURCE RECOVERY-SUMTER, INC., 755 INDUSTRIAL ROAD, P.O. BOX 1755, SUMTER, SC. Shipments may occur under EPA's consent to the notice from May 24, 2012, to May 23, 2013. This waste will be subject to all applicable federal and state laws and regulations.

#### Waste Stream 1:

Waste Description:

EPA Waste Code:

DOT Shipping Name: Solids containing flammable liquid, n.o.s.

DOT Hazard Class: 4.1 DOT I.D. No. UN3175

Total Volume to be Exported: 500000 Kilograms

Estimated Frequency: 25 loads Annually

EPA is providing this letter and attachment for your potential use and recordkeeping because your facility is listed as a receiving facility or interim receiving facility in the attached notification. If your facility is not required to submit a copy of the import consent documentation along with the RCRA hazardous waste manifest under §§ 264.71(a)(3) or 265.71(a)(3) during the period of consent listed above, then you may discard this letter and attachment.

The EPA Waste Import and Export Tracking System ID assigned to this notice is 004872/51/12.

If you have any questions regarding this correspondence, please contact Jean Shaw at telephone: 202-564-7111, telefax: 202-564-0025, or email: shaw.jean@epa.gov.

Sincerely,

Jan Shaw Wignert G. Heiss, Director

International Compliance Assurance Division

Office of Federal Activities

cc: Stanley Tam Regional Coordinator, Region 4

(Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 1. Generator ID Number 2. Page 1 of 3. Emergency Response Phone 4. Manifest Tracking Number UNIFORM HAZARDOUS 000161409 SCD036275626 WASTE MANIFEST 803-773-1400 Generator's Site Address (if different than mailing address) (Foreign Generator) 5. Generator's Name and Mailing Address (Importer) GIANT RESOURCE RECOVERY - SUMTER, INC. FIELDING CHEMICAL TECHNÔLOGÍES 755 INDUSTRIAL ROAD PO BOX 1755 3549 MAVIS ROAD GEORGINA LACKO SUMTER, SC 29150 803-773-1400 MISSISSAUGA, ON, L5C1T7 905-281-4636 6. Transporter 1 Company Name U.S. EPA ID Number FREEHOLD CARTAGE INC NJD054126164 7. Transporter 2 Company Name U.S. EPA ID Number 8. Designated Facility Name and Site Address U.S. EPA ID Number GIANT RESOURCE RECOVERY - SUMTER, INC. 755 INDUSTRIAL ROAD PO BOX 1755 SUMTER, SC 29150 803-773-1400 SCD036275626 Facility's Phone: 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 11. Total 12. Unit 13. Waste Codes and Packing Group (if any)) НМ Quantity Wt./Vol. Туре UN3175, WASTE SOLIDS CONTAINING FLAMMABLE LIQUID, N.O.S. (CONTAINS F001 F002 F003 ACETONE), 4.1, PGII 43 C DM F005 D001 D035 Secondary Emergency Response #803-773-1400 14. Special Handling Instructions and Additional Information If undeliverable, contact generator A. SE-124650-F001 BROKER NAME GHY International 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Nan 16. International Shipments Lemiston Export from U.S. Port of entry/exit: Transporter signature (for exports only): Date leaving U.S. TR ANSPORTER 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name 18. Discrepancy 18a. Discrepancy Indication Space Residue Partial Rejection \_ Full Rejection 11.1= 32850 Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

From: (803) 773-1400 Maria Pike/Records Mgr Giant Resource Recovery 755 INDUSTRIAL ROAD

SUMTER, SC 29150

Origin ID: USCA





SHIP TO: (202) 272-0167

**BILL SENDER** 

Office of Enforcement & Compliance **US Environment Protection Agency** 1200 PENNSYLVANIA AVE NW RM 6144

WASHINGTON, DC 20460

Ship Date: 06MAR13



ActWgt: 0.5 LB CAD: 4731944/INET3370

Delivery Address Bar Code



Ref# Invoice # PO# Dept#

0201

MON - 11 MAR AA **EXPRESS SAVER** 

SA RDVA

7949 0744 8486

20460 DC-US DCA





- 1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
- 2. Fold the printed page along the horizontal line.
- 3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number. Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com.FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, nondelivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim.Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental,consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss.Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

6 A 6